

Installer for Steinberg Midex drivers for Mac OS X

MIDI driver version 1.0.0b5

This is a beta driver.

System requirements:

- OS X 10.3.x or
- OS X 10.2.3 and higher.
- G4 / G5 Mac

OS X 10.1.x is not supported at all !

Supported hardware:

- Steinberg **Midex-8** and **Midex-3**

Installation:

1. Please exit all MIDI and audio applications before starting the installation !
2. Unplug all Midex devices !
3. Check if you have this file in your system:
"/System/Library/Extensions/MidexUsbFwLoaderDriver.kext", If yes, delete it !
3. Reboot your MAC.
4. Start the Disk Utility (Applications/Utilities) and run "Repair Disk Permissions".
5. Install the new driver.
6. After a second reboot plug in the Midex.

This driver uses slightly different names for the MIDI devices than the previous release used. Please delete all your old Midex devices from your MIDI Setup before using this driver.

Installed files:

There are three drivers installed by this package, the Midex Firmware Loader driver (one driver for both Midex8 and Midex3), the Midex8 MIDI driver, and the Midex3 MIDI driver. The installed files are:

/System/Library/Extensions/MidexUsbFwLoaderDriver.kext
/Library/Audio/MIDI Drivers/Midex8UsbMidiDriver.plugin
/Library/Audio/MIDI Drivers/Midex3UsbMidiDriver.plugin

Features and limitations:

Multiple Midex devices supported. No limitations noted.

Midex series OS X driver revision history

Version: 1.0.0b5 Date: 2004-10-12

Fix Permission on Mac OS X >= 10.3.

Version: 1.0.0b4 Date: 2003-08-19

CPU usage further reduced.

Worked around a Midex firmware problem which produced MIDI timing anomalies in channel messages closely following a SysEx message with LTB timestamp.

Version: 1.0.0b3 Date: 2003-07-30

Reduced the excessive CPU usage. Sustained dense MIDI In data may still provoke occasional spikes in CPU usage. This has been demonstrated to be a problem in OS X. Apple is aware of it.

Version: 1.0.0b2 Date: 2003-03-03

Fix SysEx playback bug.

Version: 1.0.0b1 Date: 2003-02-27

Supports multiple Midex devices. Performance improvements.

Version: 1.0.0d7 Date: 2002-11-27

Fixes all MIDI Out goes to port 1 bug.

Version: 1.0.0d6 Date: 2002-11-22

Bug fixes for occasional crash. Unfortunately introduced another bug which makes all MIDI Out go to port 1.

Version: 1.0.0d5 Date: 2002-10-31

Fixes a problem with the installer which resulted in the newly installed firmware loader driver not being noticed by OS X.

Version: 1.0.0d4 Date: 2002-10-24

Fixes a problem with the firmware loader driver that resulted in OS X 10.2 not loading the driver for a Midex8r2, in the case where the Midex8r2 was already plugged to the USB when the machine booted.

Version: 1.0.0d3 Date: 2002-09-27

Firmware loader driver is now a single binary supporting all Midex models.

Added support for Midex3.

No support for multiple Midex 8 devices or multiple Midex3 devices.

Version: 1.0.0d2 Date: 2002-09-05

Initial beta release.

Midex8 only, no Midex3.

No support for multiple Midex8 devices.